Weathertzation Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH3330Work Order Type: WeatherizationAudit Name: 13013SH3330

CLIENT INFORMATION

Client ID: 13013SH3330

AGENCY INFORMATION

Client ID: 13013SH3330

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: WOOD, JIM Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

DOE Weatherization Assistant Version 8.6.0 Page 1 of 5

Measures

Measure 1 Infiltration Redctn					Components				
C	Replace Weather	Ds #7, 14 & 15 Seal A/C WD #13 sill and facing (outside) strip attic stairs crawlspace door unit (1		r					
	Estimated Actual								
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1					
2	Labor	Infiltration Reduction	Each	1					
C	Other Detail						1		
L] []		
L				Measur	e Sub Total:]	Sub Total:	
	Measure 2 Repl	ace A/C window A/C unit in WD	#8 -Comp	lete 5,	Componer 000 BTU Estimated			Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Cooling Equipmen		Each	1					
2	Labor	Window A/C -	Each	1					
C	Other Detail						,		
] []		
				Measur	e Sub Total:],	Sub Total:	
	Field Notes:								

Measure 3 Floor In	ns. R-19			Componen	ts F1		ı	Inspected
Comment Install floor	insulation 1330 sq ft	R-19						
				Estimated	<u> </u>		Actual	
# Material / Labor De	escription / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	oor Insulation <i>-</i> berglass Batts - R-19	SqFt	1330					
	oor Insulation <i>-</i> berglass Batts - R-19	SqFt	1330					
Other Detail								
			Measure	e Sub Total:] ,	Sub Total:	
Measure 4 Refrige Comment 18 cu ft	rator Rplcmnt			Componen	nts		1	Inspected
# Material / Labor De				Estimated	1		Actual	
1 Refrigerators Re	escription / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
- Romgoratoro - R	escription / Comment efrigerator Rplcmnt	<i>Units</i> Each	Qty 1			Qty		Total
•						Qty		Total
•	efrigerator Rplcmnt	Each	1			Qty		Total
² Labor Re	efrigerator Rplcmnt	Each	1			Qty		Total
² Labor Re	efrigerator Rplcmnt	Each	1			Qty		Total
² Labor Re	efrigerator Rplcmnt	Each Each	1 1					Total

Measure 5 CO I	Monitor is Needed			Componen	ts			Inspected
Comment Qty 1								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	1					
2 Labor	CO monitor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	all Kitchen Exhaust Far		et and	Componen receptacle	ts			Inspected
			et and	•			Actual	Inspected
			et and	receptacle		Qty		Inspected Total
Comment Install ve	ented vent-a-hood to incl Description / Comment	ude cabin		receptacle <i>Estimated</i>	1	Qty	Actual	
Comment Install ve	ented vent-a-hood to incl Description / Comment	ude cabino <i>Unit</i> s	Qty	receptacle <i>Estimated</i>	1	Qty	Actual	
Comment Install ver # Material / Labor Health and Safety	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	ude cabino <i>Units</i> Each	Qty 1	receptacle <i>Estimated</i>	1	Qty	Actual	
Comment Install ver# Material / Labor1 Health and Safety2 Labor	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	ude cabino <i>Units</i> Each	Qty 1	receptacle <i>Estimated</i>	1	Qty	Actual	
Comment Install ver# Material / Labor1 Health and Safety2 Labor	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	ude cabino <i>Units</i> Each	Qty 1	receptacle <i>Estimated</i>	1	Qty	Actual	
Comment Install ver# Material / Labor1 Health and Safety2 Labor	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	Units Each Each	Qty 1 1	receptacle <i>Estimated</i>	1		Actual	
Comment Install ver# Material / Labor1 Health and Safety2 Labor	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	Units Each Each	Qty 1 1	receptacle Estimated Unit Cost	1		Actual Unit Cost	
# Material / Labor 1 Health and Safety 2 Labor Other Detail	ented vent-a-hood to incl Description / Comment Kitchen exhaust fan	Units Each Each	Qty 1 1	receptacle Estimated Unit Cost	1		Actual Unit Cost	

	Measure 7		or Barrier Needed ement/Crawlspace)			Componer	ıts			Inspected
C	Comment 13	30 sq	ft							
						Estimated	d		Actual	
#	Material / Lab	or	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and S	Safety	Basement / crawlspace vapor barrier	SqFt	1330					
2	Labor		Basement / crawlspace vapor barrier	SqFt	1330					
(Other Detail									
					Measure	e Sub Total:			Sub Total:	
	Field Notes:									
				Work O	rder Gra	nd Total:		Gran	d Total:	

Client ID: 13013SH3330